



Date: Wednesday, 11/07/2007 9:48:58 AM
 User: Linda Lacelle

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : REWORK
Job Number : 33464	
Estimate Number : 10804	
P.O. Number : N/A	Part Number : D25763
This Issue : 11/07/2007 S.O. No. : N/A	Drawing Number : D2576-3
Prsht Rev. : NC	Project Number : N/A
First Issue : N/A	Drawing Revision : N/A
Previous Run : 00015	Material : N/A
Written By : 	Due Date : 27/07/2007
Checked & Approved By : 	Qty: 100 Um: Each
Comment :	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1
 REMOVE FROM STOCK
 D2576-3 B 31925

BE 07.07.16

2.0	D25763	Step (Machining Detail)
-----	--------	-------------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 100.0000 Each(s)
 Step (Machining Detail)

3.0	MILLING CONV.	CONVENTIONAL MILLING MACHINE
-----	---------------	------------------------------



Comment: CONVENTIONAL MILLING MACHINE

OPEN UP 0.50" WIDE SLOTS PER ATTACHED

SD 07.07.16

(100)

4.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

N/A

SD 07.07.16

(100)

5.0	QC6	SECOND CHECK
-----	-----	--------------

QC6



Comment: SECOND CHECK

07.07.16
 pr QSPOM

Date: Wednesday, 11/07/2007 9:48:58 AM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: REWORK

Job Number: 33464

Part Number: D25763

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

RE IDENTIFY USING NEW B/N
(STOCK IN LANDING GEAR - BARCLAY)

BB 07-07-16

7.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE


100

12/16/23

Job Completion



9 07-07-18



D2576-3 RE-WORK

L Lacelle

From: Marc Bellavance [mbellavance@dartaero.com]
Sent: July 11, 2007 8:36 AM
To: 'L Lacelle'
Subject: D2576-3 Step Re-work
Attachments: D2576-3ReWork.pdf

Linda,

Here are the instructions for the D2576-3 Step re-work:
Open up 0.50" wide slot as per attached sketch.

116

Marc Bellavance
Internal Support/Product Improvement

DART aerospace Ltd.

Tel: 613-632-5200 Ext. 240
Fax: 613-632-9311
E-mail: mbellavance@dartaero.com
Web: www.dartaero.com

11/07/2007